

**From:** [Miller, Garyg](#)  
**To:** [Sanchez, Carlos](#)  
**Subject:** FW: San Jacinto - Pontoon  
**Date:** Wednesday, March 16, 2016 7:14:00 AM  
**Attachments:** [SanJac Pontoon Maintenance 20160314.pdf](#)

---

Some "rocking" pics

Gary Miller  
Remedial Project Manager  
EPA Region 6 – Superfund Division (6SF-RA)  
214-665-8318  
[miller.garyg@epa.gov](mailto:miller.garyg@epa.gov)

---

**From:** David Keith [mailto:[dkeith@anchoragea.com](mailto:dkeith@anchoragea.com)]  
**Sent:** Tuesday, March 15, 2016 3:54 PM  
**To:** Miller, Garyg <[Miller.Garyg@epa.gov](mailto:Miller.Garyg@epa.gov)>  
**Cc:** Dave Moreira ([dmoreira@wm.com](mailto:dmoreira@wm.com)) <[dmoreira@wm.com](mailto:dmoreira@wm.com)>; Phil Slowiak <[philip.slowiak@ipaper.com](mailto:philip.slowiak@ipaper.com)>; Holly Samaha <[hsamaha@anchoragea.com](mailto:hsamaha@anchoragea.com)>; John Laplante <[jlaplante@anchoragea.com](mailto:jlaplante@anchoragea.com)>; Wendell Mears <[wmears@anchoragea.com](mailto:wmears@anchoragea.com)>  
**Subject:** FW: San Jacinto - Pontoon

Gary – As requested, please see the attached photos from Holly.

Regards,  
David

---

**From:** Holly Samaha  
**Sent:** Tuesday, March 15, 2016 2:39 PM  
**To:** David Keith <[dkeith@anchoragea.com](mailto:dkeith@anchoragea.com)>  
**Subject:** San Jacinto - Pontoon

Hi David,

See attached for photos of Benchmark using the pontoon boat for maintenance work yesterday. The first photo shows the skid steer loading the pontoon with armor rock, and the other two show the rock being placed in the East Cell. Let me know if you need anything else.

Holly Samaha

ANCHOR QEA, LLC  
[hsamaha@anchoragea.com](mailto:hsamaha@anchoragea.com)  
10701 Corporate Dr., Suite 240  
Stafford, TX 77477  
Office: 281-565-1133 Ext. 203  
Cell: 225-288-4162



9769078

ANCHOR QEA, LLC

[www.anchorqea.com](http://www.anchorqea.com)

Please consider the environment before printing this email.





03/14/2016 10:24



